## Oil Field Environmental Incident Summary

Responsible Party:

Well Operator: CONTINENTAL RESOURCES, INC.

Well Name: LONESOME DOVE 1-21 SWD

Field Name: CEDAR HILLS Well File #: 90086

Date Incident: 1/20/2007 Time Incident: 15:30 Facility ID Number:

County: BOWMAN Twp: 131 Rng: 106 Sec: 21 Qtr: NW NW

Location Description: 1.29 miles east of Duffield CTB in the NENW Section 18-132-106.

Submitted By: Mike Swift Received By: Mark Bohrer

Contact Person: MIKE SWIFT

PO BOX 1032 ENID, OK 73702

General Land Use: Pasture Affected Medium: Soil and Water

Distance Nearest Occupied Building: 1 Miles
Distance Nearest Water Well: Miles

Type of Incident Pipeline Leak

Release Contained in Dike No Reported to NRC: Yes **Spilled** Units Recovered Units **Followup Units** 0 0 0 Oil barrels barrels barrels 5000 0 0 Brine barrels barrels barrels Other 0 barrels 0 barrels 0 barrels

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Surface water contamination.

Areal Extent:

30' x 30', 3' x 20'.

## Potential Environmental Impacts:

Probably very minimal because of dilution.

## Action Taken or Planned:

Repaired line by replacing one joint and a partial joint and put back in service. The leak occurred just inside metal creek crossing sleeve. Had to cut metal creek crossing sleeve back about 2' to repair fiberglass line. Monitor flow in line with meters at each end. Had meter failures recently and inexperienced lease operator noticed shortage and thought meter was malfunctioning. When he went to repair he found it was not malfunctioning.

Wastes Disposal Location:

Agencies Involved: